

FAR 91.207 should be updated to cover the new 406 MHZ ELT'S
The change should include actual decoding and reading of the
406 ELT's I.D. number and GPS Lat/Long by independent Test Equipment
to verify that the 406 ELT is actually transmitting the correct
I.D. number and the actual Lat/Long from a GPS receiver thru the
ELT antenna.